






Царговый пояс Raibox с ПМ




Раїтон
кроватьи и матрасы










* для размеров 80, 90, 120, 140
** для размеров 160, 180, 200

П - 1 компл.




Р - 1 шт.






Для размеров 80, 90


Н1
1x




Н2
4x



Н3
3x




О1
4x




Для размеров 120, 140

Н1
1x




Н2
7x




Для размеров 160, 180, 200

Н1
2x



Н2
10x




Н4
2x




⊙ - гайка «УС»
○ - гайки «УС» нет

1




2


x4




3



4a (80, 90, 120, 140)




4b (160, 180, 200)




- ⊙ - гайка «УС»
- - гайки «УС» нет

5




6




7a

(80, 90)




7б

(120, 140, 160, 180, 200)




8a


(80, 90, 120, 140)




8b

(160, 180, 200)












10





11









Следует проводить смазку
трущихся частей механизма
не реже 2 раз в год

